



Product: SiS USB2 Driver

Date: 08/18/2003

Document Type : Release Note

Driver. No.: 1.04

SiS USB2 Driver [V1.04]

1. The USB2 logo driver v1.04, no USB driver update from USB driver v1.03.

Modification

1. Fix the Patch_98.exe and Patch_Me.exe can not be used on SiS964 southbridge chip issue.